Yocom-McColl Testing Laboratories, Inc.

540 West Elk Place • Denver, Colorado 80216-1823 USA
PHONE (303) 294-0582 • FAX (303) 295-6944
EMAIL: ymccoll@ymccoll.com

Sirolan Laserscan
Micron Test Report

Xanadu Farm/Pamela Ray
669 Emerson Street
Denver CO 80218 USA

05/24/10

Test No: 375476

Animal and Sample Description

Animal Name:	Barnabus	**Animal ID:**	XXXXX
Breed:	Alpaca(Huacaya)	**Sample Location:**	Side
Sex:	XXXXX	**Sample Date:**	05/07/10
Color:	XXXXX	**Age:**	07/25/02

Laboratory Data

Mean Fiber Diameter:	20.0 microns
Standard Deviation:	3.9 microns
Coefficient of Variation:	19.4 %
Fibers Greater Than 30 microns:	2.2 %



This Test Performed According to I.W.T.O Method 12

Yocom-McColl Testing Laboratories, Inc.
540 West Elk Place • Denver, Colorado 80216-1823 USA
PHONE (303) 294-0582 • FAX (303) 295-6944
EMAIL: ymccoll@ymccoll.com

Stralan Laserscan
Micron Test Report

11/10/03

Maple Brook Farm Alpacas/Mike & Robin Tierney
593 East Mountain Road
Westfield MA 01085 U.S.A.

Test No: 236470

Animal and Sample Description

Animal Name:	Maple Brook Barnabus	Animal ID:	840936
Breed:	Alpaca(Huacaya)	Sample Location:	Side (R)
Sex:	Male	Sample Date:	05/22/03
Color:	Beige	Age:	07/04/02

Laboratory Data

Mean Fiber Diameter:	12.8 microns
Standard Deviation:	2.6 microns
Coefficient of Variation:	20.4 %
Fibers Greater Than 30 microns:	0.3 %



This Test Performed According to I.W.T.O Method 12

Maple Brook Barnabus
One Year Histogram