Yocom-McColl Testing Laboratories, Inc.

540 West Elk Place • Denver, Colorado 80216-1823 USA
PHONE (303) 294-0582 • FAX (303) 295-6944
EMAIL: ymccoll@ymccoll.com

Sirolan Laserscan
Micron Test Report

Broken Road Alpacas/Joe and Stacy Miller
740 R St.
Geneva NE 68361-1013 USA

04/11/13


Test No: 451743

Animal and Sample Description

Animal Name:	Dedra	**Animal ID:**	XXXXX
Breed:	Alpaca(Suri)	**Sample Location:**	Side
Sex:	XXXXX	**Sample Date:**	XX/XX/XX
Color:	XXXXX	**Age:**	XXXXX

Laboratory Data

Mean Fiber Diameter:	18.7 microns
Standard Deviation:	6.0 microns
Coefficient of Variation:	32.3 %
Fibers Greater Than 30 microns:	6.7 %



This Test Performed According to I.W.T.O Method 12